

2006 TJ Unlimited. I have an annoying noise coming from the driveline known as the "Angry Sparrows". The stock front drive shafts double Cardan joint failed. The double carden joint is a Spicer but the joint at the axle is Jeep. Jeep mixes components when they build the front shaft. The front joint is part Spicer and part Saginaw. The correct replacement part# from Spicer is SPL25-4X. This joint replaces the stock front joint with one that has retainer clips on the inside. The stock unit has pins that go through the sides of the yoke to hold the end caps and must be drilled out before pressing the caps out. Im going to get EC Driveline to rebuild the shaft with all new Spicer joints and a new front yoke so all the joints will be the same type for ease of replacement parts. Depending on the cost to rebuild, I may just order a complete new HD front shaft from Tom Woods.